



SVS-02-13
5/29/2013

TO: ALL ISUZU POWERTRAIN DISTRIBUTORS & DEALERS: SERVICE, WARRANTY & PARTS PERSONNEL

SUBJECT: 6HK1 OIL PAN GASKET PARTS CHANGE AND INSTALLATION PROCEDURE

Isuzu Motors America, LLC PowerTrain Division (ISZAPT) has implemented an oil pan gasket change on the 6HK1 engines due to parts commonization. The original oil pan gasket will be replaced with a liquid type gasket. Please refer to the parts interchange chart and pictures below for the needed details. This parts change was implemented in production engines in March 2013.

Parts Interchange Information

Affected Parts	Current Parts	Qty	New Parts	Qty
PACKING; OIL PAN	1113671310	1	2-90067-004-0	--

Best Regards,

Mike Ruiz

Service Specialist

