



SVS-04-12  
5/18/2012

**TO: ALL POWERTRAIN DISTRIBUTORS AND DEALERS**

**SUBJECT: IDE-2410 4HK1/6HK1 WORKSHOP MANUAL CORRECTIONS UPDATE**

This is notification a special service tool has been updated in the 4HK1/6HK1 Workshop Manual IDE-2410. The manual indicates tool part number 5-8840-2703-0, which needs to be replaced by part number 5-8840-9061-0. These tools are not interchangeable. The corrections have been made to the online manual (pages 1A-128, 1A-129, 1A-133, 1A-135, 1A-136 and 1A-138) and uploaded to the [www.isuzuengines-info.com](http://www.isuzuengines-info.com) site in the Service and Parts Folder, within Workshop Manuals. If you have this manual in print form, please take note of the changes. If corrective stickers are required please request these via email to Laura Chesney, Market Communications Coordinator, at [laura.chesney@isza.com](mailto:laura.chesney@isza.com).

