

To: ALL ISUZU DISTRIBUTORS AND SERVICE DEALERS
Subject: UPDATED FUEL SUPPLY AND RETURN LINE BANJO BOLT FOR ALL 4JJ1 ENGINES

Isuzu Motors America, LLC strives to keep information up to date for our network. There has been a recent update regarding the fuel supply and return line banjo bolt for all 4JJ1 engines. Please see pictures below.



The new Banjo Bolt features a Boss in between the supply and return lines, which will require copper washers/gaskets to be installed on both sides of each fuel line. (Please note for purchasing and stocking, copper washers/gaskets needed).

Please note the updated part number and quantities below.


Affected Parts	Current Parts NO.	Q'ty	New Parts NO.	Q'ty
RELIEF VALVE	8980749550	1	8975511850	1
FUEL PIPE PACKING	8982513450	3	8982513450	4



Current



New



New Layout

