

SERVICE & PARTS BULLETIN

SVS-23-07 8/22/2007

TO: ALL ISUZU DISTRIBUTOR & DEALER SERVICE & PARTS PERSONNEL

SUBJECT: FUEL FEED PUMP DESIGN CHANGE

BACKGROUND INFORMATION

Isuzu Motors Limited has implemented a design change to existing fuel feed pumps that use the tappet roller. Fuel feed pumps using the tappet roller are being replaced with fuel feed pumps that use a push rod. Although this new style push rod pump is physically different, it is a direct replacement for the discontinued tappet roller pump.



Tappet Roller Type



Push Rod Type (New Design)

MODELS AFFECTED

All feed pumps on all production engine models and service parts.

ACTION REQUIRED

No special action required. Do not hesitate to install this feed pump on your customer's injection pump.

If you should have any questions please contact your service and parts representative.

Best Regards,

The ISZAPT Service & Parts Team